





Troubleshooting



Know your 4 Quadrants



Cavitation?
Restriction?



Cavitation?
Restriction?


LIBERTY

SPRAY FOAM EQUIPMENT & SUPPLIES


**Before looking at the gauges,
you must know what chemical
is coming out of your gun.**

LIBERTY


SPRAY FOAM EQUIPMENT & SUPPLIES



If gauge is below normal, the problem lies in quadrant **1** (supply).




LACKING A




LIBERTY


SPRAY FOAM EQUIPMENT & SUPPLIES



If gauge is above normal, the problem lies in quadrant **3** (hose/gun).




LACKING **A**




LIBERTY

SPRAY FOAM EQUIPMENT & SUPPLIES




LIBERTY

SPRAY FOAM EQUIPMENT & SUPPLIES



LIBERTY


SPRAY FOAM EQUIPMENT & SUPPLIES



REPAIR PROPER QUADRANT OF
EQUIPMENT

LIBERTY

SPRAY FOAM EQUIPMENT & SUPPLIES



SPRAY PERFECT FOAM!